



Revision Date: 16 APRIL 2024

Prepared For: SYNRAD 48-1 CO₂ LASER CUSTOMERS

Subject: PRODUCT CHANGE NOTIFICATION
PCN 004-2024: 48-1 CHASSIS HOLE REMOVAL

Prepared by: SYNRAD PRODUCT MANAGEMENT & ENGINEERING

SYNRAD PCN 004-2024: 48-1 CHASSIS HOLE REMOVAL

There are two holes in the 48-1 RF chassis that are not needed and therefore will be removed. The holes are currently filled with non-functional screws, as shown in Figure 1.



Figure 1. Two holes in the 48-1 chassis are filled with non-functional screws.

This change will not impact the functionality, performance, or reliability of the laser.

Please contact your local Novanta account manager if you have any questions or concerns.